

Problem 1.21

Amplification factors on a voltmeter used to measure the vibration output from an accelerometer are given as 10, 50, and 100. What are the decibel steps?